



Wrong cable used on PROFIBUS DP (RS485) segments

1) Solution using Procentec COMbricks unit with SALT module together with PEPPER active terminator



2) Solution using two Procentec PEPPER active terminators set up with ProfiTrace oscilloscope function



This drawing has been issued for information purposes only. Under NO circumstances does Verwer Training & Consultancy Ltd warrant the accuracy of this information. Therefore any use and/or reliance on this information is at the user's own risk

Copyright © Verwer Training & Consultancy Ltd 2013.
This drawing may not be reproduced without VTC's written permission. This drawing and associated information is confidential to VTC.

Client:

File name:

Rev	Date	Description
1	10/03/13	Initial issue



Verwer Training & Consultancy Ltd
Professional Training & Consultancy for the Automation & Control Industry

Title: Use of SALT and PEPPER active terminators to solve wrong cable problems

Drawn: A. Verwer

Drawing No:

Date: 10 April 2013

Page size: A4

Approved: